

## Enamelled steel articles handcrafted by IBILI.



The following defects are frequently visible when handcrafting enamelled steel articles. They do not compromise the integrity of the parts, are difficult to avoid and considered as normal.

- Small unglazed specks on the main body.
- Unglazed lines on thin edges and holes
- Unglazed lines or specks in folds and joints on handles, nozzles or other parts welded to the main body.

